Scott II-48—25,005—16-3-14.

Public works (1914) Department.

Mis SERIES.

G.O. No. 399-400 I

DATED 18.8.14

[Despatch Abstract.]

Photograph of a Syphon well drop in the Palayamparavoo channel ——
Furnishing the Government of India with eight unmounted copies of ——

Indexed
[illegible]
18/8

Sectt. II-9—24,002—19-4-13.

DEPARTMENT.

Photograph of a Stypher bellows in the new palayam Panrooche

CURRENT FILE.

CONTENTS.

Current No.	From	Number.	Date.	Pages.
	SE VI circle	341ce/1720	4.3.14	
	To SE VI	1325/14-1	26.3.14.	
	From SE VI	805ce/1720	5.6.14	
	SE VI	886ce/1720	5.6.14	
	SE VI	1007ce/1720	17.7.14	
	SE VI	1063ce/1720	30.7.14.	

[P.T.O. FOR PUT UP PAPERS.

Stock Form No. 141.
4,000—15-11-11.

PUBLIC WORKS DEPARTMENT.

CURRENT No.

Received .... 191 .

Registered .... 191 .

ENCLOSURES. Plans No.
Others No. 1 (Sent registered)

Passed on by Registering Clerk ...
" " U. R. Clerk ...
" " Referencer ...
" " Record Superintendent.
" " Drafting Officer ...

SPARE COPIES.

CHIEF ENGINEER FOR IRRIGATION. 5 MAR 1914 No. 1325/14

DG

[illegible] under cardboard

Subject.

Photo of Syphon well drop in the new Palayamperavo Channel - Forwards a — with a request to be informed if any more Copies & the negative are required.

No. 341-CE / 1720

Station, Trichinopoly, *Dated the* 4" March 1914.

From (Name) M. R. Kharegat, Esq., A.M.I.C.E.,

(Designation) Superintending Engineer, VI Circle,

To ~~The Chief Engineer~~ for Irrigation, ~~The Secretary~~ to the Government of Madras,

Public Works Department.

Reference:- Your No.3253-A/13-1, dated 19th Sept'r 1913.

----

x Dis 2424 / 1-12-13

x p.28 of Dis No 2424 / 1.12.13

Sir,

I have the honour to forward a photo of the drop as requested. I request to be informed if any more copies and the negative are required.

2. The delay in the submission of the photo is due to the difficulty in getting a photographer to go to the site

2

at a reasonable rate. Eventually Mr.Johnson had to be brought down from Periyar to take the photo.

I have the honour to be,

Sir,

Your most obedient servant,

T. Krishnaswami Iyer
for Superintending Engineer, 3.3.14

VI Circle.

3.3.14

Memo. 1325/14.1 d/26.3.14.

—

pp1-2 CS – With ref. to letter N. 341 CE d/4.3.14 from the 1720 S.E. VI submitting a photo of the syphon well drop on the new Palayamparavu chl: the E.I. has the honour to observe that the chl: ~~appears to be scoured~~ ~~is a bit rugged~~ but is scoured down stream but this does not appear to be due to scouring action. The S.E. is requested to state if this is attributable to the new work

To be reminded on 24.5.14 [illegible] 26.3.14

2 It is not known why the entry to the well drop is not a trapezoidal notch & why it is cut back from the well instead of being merely a notch in the side of

4

the well steining. It [is] also not clear of the width of the earthwork behind the wall [is] sufficient for cart traffic. The S.E is req[uested] to submit a full report on these [illegible] with plan & ~~estimate~~ report ~~[illegible]~~ accompanied the estimate.
~~[illegible]~~
~~[illegible]~~
~~[illegible]~~

A dozen copies of the photo ~~may be sent as soon as possible~~ are also required ⊗

[signature]

[signature] 24/3/14

⊗ The negative may be retained in the E.E's office

DESPATCHED
Date 30.3.14
Enclos —

2.

The S.E VI

[initials] 26.3.14

5

R.F.D.—80—(l).

PUBLIC WORKS DEPARTMENT.

C1325/14

CURRENT No.

CHIEF ENGINEER FOR IRRIGATION. 6 JUN 1914 No. 3219/14 C

ENCLOSURES. { Plans No. / Others No.

Received .... 191 .

Registered .... 191 .

Total. 1

Passed on by Registering Clerk ...

SPARE COPIES

" " U. R. Clerk ...

" " Referencer ...

" " Record Superintendent.

" " Drafting Officer ...

Subject.

Syphon well drop in the new Palayamperavoo channel. Forwarding report in connection with the ——.

No. 805-CQ

1720

Station Trichinopoly, *Dated the* 5 June 1914

From (Name) Mr. R. K. Rangachari Engineer A.M.I.C.E.

(Designation) Superintending Engineer, ... Circle

To ~~The Secretary~~ The Chief Engineer for Irrigation to the Government of Madras,

Public Works Department.

DC

6

Copy of letter No.521-S.E., dated 18/19th May 1914, from M.O'Brien, Esquire, Executive Engineer, Madura Division, to the Superintending Engineer, VI Circle, Trichinopoly.

With reference to your No.3015/1720 dated 15th April - 1914, I have the honour to report as follows:-

2. The erosion in rear of the well drop may or may not be attributable to the new work. It probably is not. The -- channel was dug in 1908 and the drop built in 1912. There is wet cultivation all round the site and water is always percolating into the channel below the drop causing slips. The revetment below the drop was not well built and was not taken high enough. If it were taken about another 1'-6" higher much of the scour would be stopped.

3. The entry to the well is a trapezoidal notch in the side of the well. On the day the photo was taken a little water was probably passing over the top of the notch; on this account probably the notch did not appear clearly in the photo.

4. The width of the earthwork behind the well is sufficient for cart traffic and carts are reported to pass that way now.

5. A blue print of the sanctioned plan is sent herewith. There is no special report on the work.

No. 805 CA / 1720 dated 5 June 14 — Enclosure:- 1 Blue Print M.No.306-A / 1910

Forwarded to the Chief Engineer for Irrigation, with reference to his No.1325/14-1 dated 30th March 1914.

The Executive Engineer, Madura Division, is being requested to forward the dozen copies of the photo required.

S. Krishnaswami

for Superintending Engineer,
VI Circle.

4 C.f.

M 4421, 4572 7/6/14 CE

28 6035 MAY 1914

C.F. 88—1,002—26-11-13.

C/1325/14

CHIEF ENGINEER FOR IRRIGATION. 6 JUN 1914 No. 3220/14 C

Public Works Department.

Irrigation Branch.

REMINDER. 1325/14.

To

The Superintending Engineer Sixth Circle.

The undersigned has the honour to invite ~~is directed to invite~~ ~~invites~~ attention to the communication noted in the margin and to request that this reminder may be returned at once with information as to—

Memo No. 1325/14 dated 26-3-14

1. the stage at which the matter now is,
2. the date by which a reply may be expected, ~~and~~
3. ~~the circumstances which have caused the delay.~~

2. It is requested that the reply to this reminder may be sent not later than 6-6-14

Office P.W.D. (I) P.K. Subbaaiyar Signature. 26.5.14

Station Chepauk ~~Designation~~

Dated 26-5-14 27 for chief Engineer for Irrigation. 26.5.14

SUBJECT.

Photo of the syphon well drop in the new Palayamperavoo channel Requesting to submit a full report on certain points raised in connection with the — & to send a dozen copies of the photoes.

REPLY.

No. 806 CE / 1720 Dt 5 June 1914

To

THE Chief Engineer for Irrigation Madras

Sir,

I have the honour to inform you that the report called for, has been separately submitted Vide this office No. 805 CE / 1720 of 5.6.14

I have etc.

S. Srinivasaswamy

For Supdg Engineer VI Circle

4/6/14. 4/6/14


M. No: 306 A
1910
5 FT WELL DROP
AT 8976' OF
NEW PALIAMPARAVOO CHANNEL
SCALE 1/100
PLAN
C.R. No: 351/1213
TOP OF BANK
BERM
DRAIN
ON A.A
CROSS SECTION OF TUNNEL
ON C.C.
LONGITUDINAL SECTION
BED OF CHANNEL +69·55
PUDDLE CLAY
G.L +71·54
F.S.L +67·05
+64·55 BED OF CHANNEL
VIDE INSPECTION NOTE OF E.E. FOR JULY 1911
D.S. APPROVED IN S.E.'s No.
EXECUTIVE

SUPERINTENDING ENGINEER'S OFFICE
4421
20 MAY 1914
ENGR. P.W.D.
VI CIRCLE, TRICHINOPOLY.

Acknowledgment ... Receipt
No 329 ... 6.6. 1914

9

PUBLIC WORKS DEPARTMENT.

Irrigation Branch.

SUPERINTENDING ENGINEER'S OFFICE ... NOPOLY.
1329
13 JUL 1914

CE

REMINDER. 1325/14.

To

The Superintending Engineer
VI Circle

p.s.

THE undersigned has the honour to invite attention to the ~~Order~~ SE's R.O.C.* No. 805 CE dated 5. 6. 14 and to request that this reminder may be returned at once with information in the margin as to—

(1) the stage at which the matter now is, and

(2) the date by which a reply may be expected, ~~and~~

(3) ~~the circumstances which have caused the delay.~~

2 It is requested that the reply to this reminder may be sent not later than 22. 7. 14.

MADRAS,
11. 7. 1914.

M S Venkataramanayya
for *Chief Engineer for Irrigation.*

GV
11. 7. 14

* *Subject.*

Syphon well drops in the new Palayar Permon channel stating that the Ex Eng had been requested to send a dozen copies of the photograph of the ——.

1325/14
CHIEF ENGINEER FOR IRRIGATION.
18 JUL 1914
No. 4189/14 - C

REPLY.

No. 1007 CE / 1720 d/ 17. July 14

To

THE CHIEF ENGINEER FOR IRRIGATION,

Madras.

(1) The photographs are still awaited from the Executive Engineer and an urgent reminder is being sent to him.

(2) Will be answered on receipt of reply from the Exe. Engineer.

[signature] 17/7/14
for Supg. ~~Engineer~~
VI Circle

SE
15. 7. 14

DE2

10

Stock Form No. 141.
4,000—15-11-11.

PUBLIC WORKS DEPARTMENT.

CURRENT NO.

ENCLOSURES. Plans No.
Others No. 12 (sent registered).

Received .... 191 .

Registered .... 191 .

✓ Passed on by Registering Clerk ...

Total. 12 1325/14

SPARE COPIES.

CHIEF ENGINEER FOR IRRIGATION. 31 JUL 1914 No. 4442/14—C

" " U. R. Clerk ...

" " Referencer ...

" " Record Superintendent.

" " Drafting Officer ...

Subject.

Syphon well drop in the Palayampanaru channel.
Forwards 12 prints of view of the ——.

No. 1063-CE
1720

Station Trichinopoly, *Dated the* 30 July 1914

From (Name) M. R. Khanagal Esquire. A.M.I.C.E.

(Designation) Superintending Engineer VI Circle

To *The Chief Engineer* for Irrigation. ~~*The Secretary*~~ *to the Government of Madras,*

Public Works Department.

Sir,

DC2

11

Copy of letter No.758 S.E. dated 16th July 1914, from M. O'Brien Esquire, Executive Engineer, Madura Division, Madura, to the Superintending Engineer, VI Circle, Trichinopoly.

With reference to your No.805 C.E./5th June 1914, I have the honour to forward herewith 12 prints of view of 5 feet well drop at 8000 feet in the new Palayampuravoo channel, as called for therein.

No. 1063 CE/1720 dated 30 July 1914. (Enclosures:-- 12).

Forwarded together with the enclosures to the Chief Engineer for Irrigation in continuation of this office No.1007 C.E/1720 dated 17th July 1914.

699

Superintending Engineer,

VI Circle.

p1-2cf From the Supdg Engr VI circle 341ca/1720 dated 4.3.14.
p3-4cf To SE VI No. 1325/14-1 dated 26.3.14
p5-6cf From SE VI 805ca/1720 dated 5.6.14
p7cf Reminder to SE VI dated 27/6 in and reply thereto 806ca/1720 dated 5.6.14
p9cf Reminder to SE VI dated 11.7.14 and reply no 1007ca/1720 dated 17.7.14
p10-11cf From the Supdg. Engr VI No 1063ca/1720 dated 30.7.14.

Note by the Chief Engineer for Irrigation. No. 1325/14-2 dated .

Submitted to Government.

2. Eight copies of the photograph of the Syphon well drop in the Palayam-madam D? -puravoo channel are herewith forwarded for submission to the Government of India.

[signature] 15/7/14

DE I.

To
The Jt. Secretary to Govt
P.W.D (Irrigation).

[initials] 4.8.14 [initials] 4.8.14

Office of the Chief Engineer for Irrigation.

NOTES.

ubject:—

Photo of syphon well drop in the new Palayam parumor chl: —

[C1325]/14. I. pp1-2 Cf

From the S.E VI No. 341 C.E / 1920 of 4.3.14

D.E.I

The S.E submits a photo of the syphon well drop called for in memo 3253 A/13-1 of 9.9.13 & requests to know if any more copies & the negatives are required.

p28 of the proof-copy kept below

For orders.

[illegible]

Sd 6.3.14. Int 6-3-414

[illegible] 20.3/14

E.1

The channel is a bit jagged downstream but it does not appear to be due to scouring action.

The S.E. might be asked to send 10 more copies, 8 for Govt. of India & 2 for E.1.

[signature] 20/3/14

I don't know why the entry to

the well drop is not a trapezoidal notch & why it is cut back from the well instead of being merely a notch in the side of the well steining.

It is not clear if the width of the earth work behind the well is sufficient for the cart traffic.

The S.E. might send plan & report to estimate and a dozen copies of the printed report on the above points & also on the erosion below the work noticed by D.E. I & say if this is attributable to the new work.

[signature]

20/3/14

D.E.I.

A draft memo. to the S.E. is put up for approval:

Orders are requested if the S.E. may be asked to send the negative.

[signature] 20/3/14

Kindly send negative to S.E.

Thro' T

[signature] 23/3/14

Please send copy with plan

[signature] 24/3

Please see page 4

E.C.

15,000—7-1-14.

NOTES.

1325/14

Memo to S.E. VI. No. 1325/14-1 of 26.3.14.

~~Reminder sent to S.E. VI 25.5.14.~~

Reminder
DESPATCHED
Date 27.5.1914
Enclos. —

M.E.II

A draft reminder to the S.E. VI is put up for approval and orders to issue.

K.S.R.
25.5.14.

GD
26.5.14

Issue
PMS
26.5.14

Reminder to S.E. VI despatched on 27.5.1914

p6b cf
From the S.E. VI circle 805 CE of 5.6.14

p7 cf
— " — 806 CE of 5.6.14.

DE1

Submitted for orders

p.6. c.f.
The receipt of the (copies of the) photographs may be awaited.

Say Await
12/6/14.

Kly 10/6/14

T.R.
8.6.14

GD
8.6.14.

ME1

Reminder
DESPATCHED
Date 11.7.1914
Enclos. —

A draft reminder to the S.E. VI is submitted for approval & orders to issue.

K.S.R.
11.7.14.

11.7.14

Issue

GD
11.7.14

MACE
11.7.14.

Reminder to S.E. VI of 11.7.14.

p9cf
From the Supg Eng VI circle 1007 CE / 1720 of 17.7.14.

DE1

Submitted for perusal.

p9cf
In the circumstances stated

30 Reams—3-4-31.

1325/14

4

P.W.
~~REVENUE~~ DEPARTMENT.

The file may lie over for one month pending the receipt of a further communication from the Supg. Engineer.

Jkl 21.7.14 Gw 21.7.14 [illegible] 27.7.14

[initials] 23/7/14

pp 10-11 cf — From the Supg. Engr. VI Circle. 1063 C.R. 1/20 d. 30.7.14

DE1.

The Supg. Engineer forwards a ~~one~~ dozen copies of the photograph of the Syphon well drop in the Palayampuravoo channel. As ordered by D.E.1. eight copies of the Photograph may be forwarded to the Govt. of India and the rest may be recorded in T. section.

p 12 f

A draft order + letter forwarding the copies of the Photograph to the Govt. of India are submitted for approval and orders to issue

Thought.

Jkl 6.8.14 Gw 6.8.14 7

As the exact date of completion of the drop is not known,* it has been taken as 1912 & entered on the back of a copy of the photo in accordance with letter No. 521 S.C. dated 19th May 1914.

[initials] 15/8/14

* Vide note of D.E.1 below

Sent back to Madras on 18/8/14

Note 2 copies of photo putting in a [illegible]. on one of which, the description has been printed in pencil for approval.

MR 13/8/1914 [initials] 13.8.14

Scott. II—10 (a)—7,000—4-13.

P. W(I)/ DEPARTMENT.

Photograph of a syphon well drop into the Palayampamu(?) channel: Furnishing the Govt. of India with eight unmounted copies of ——.

Photos
Maps & plans
Syphon

not print(?)

READ AGAIN G.O. No. 337-338 I, dated 18 . 7 . 1914.

" " " " ...., " .... 191 .

READ ALSO:—

C. No. Note from the Chief Engineer for Irrigation, No. 1325/14-I, dated 7. 1914.

" " ...., " " ...., " ...., " .... 191 .

" " ...., " " ...., " ...., " .... 191 .

ORDER. No. 379 I, dated 18 · 8 · 1914.

Mis.

The Photographs submitted by the Chief Engineer for Irrigation will be forwarded to the Government of India.

2. The following letter will be sent:

[H E letter No 400 I. 18 · 8 · 14

To The Chief Engineer for Irrigation. with copy of the letter

DESPATCHED
Date 18 · 8 · 1914
Enclos. 1

DESPATCHED
Date 18 · 8 · 1914
Enclos. one cover containing 8 photos

2

To

The Secretary to the
Govt. of India
P.W.D.

Sir,

In continuation of my letter no. 3381 d/ 18.7.14. I am directed to forward eight unmounted copies of a Photograph of a Syphon well drop in the new. Palayampuravoo chl. taking off from the Suraliyar in the Madura District. The description has been printed on one copy of the Photograph as directed in Mr Hawkin's letter No. 1600 d/ 15.10.13.

Not put up.

Enclosure:
Eight copies of the Photograph.

Vide letter in G.O. No. 6051 / 4.11.13

2. I am to add that photographs of some more works are awaited from

3

from Superintending Engineer
These will be forwarded
to you on receipt.

I have the honour
etc.
[illegible] 15/8/14

[illegible] 1318

[illegible] 7.8.14 [illegible] 7.8.14

DESPATCHED
Date 18.8.1914
Enclos. one Cover containing 8 [illegible]